



Precise thinking

Discontinued Products List

NovAtel Inc.

Phone: 1-800-NOVATEL
403-295-4500

Fax: 403-295-4901

Web: www.novatel.com

Email: sales@novatel.com

Mail: NovAtel Inc.
1120 - 68th Avenue NE
Calgary, Alberta
Canada T2E 8S5

The products in this list are no longer available for sale from NovAtel. NovAtel will continue to offer Technical Support and Repairs for these products until the Standard End of Service date.

BeeLine, GPStation, GrafNav/GrafNet, Inertial Explorer, MEDLL, Narrow Correlator, NovAtel, NovAtel OnBoard, OEMV, ProPak, RT-2, and Waypoint are registered trademarks of NovAtel Inc. AdVance, ALIGN, EuroPak, FlexPak, GL1DE, Pinwheel, RT-20, SafeTrak, SPAN, and Vision Correlator are trademarks of NovAtel Inc.



Card

Euro-L5 & EuroPak-L5

End of Life Announcement: 3 November 2005
Last Time Buy: 3 November 2005
Standard End of Service: 3 November 2010
Replacement Product: EuroPak-15a receiver

Affected Models
 01017286

OEM4-G2 Card

End of Life Announcement: 30 October 2006
Last Time Buy: 28 February 2007
Standard End of Service: 31 October 2011
Replacement Product: OEMV-3

Affected Models

01017567	LBAND-OEM4-G2
OEM4-G2-3111R	OEM4-G2-3111R[GA]
OEM4-G2-3111R-API	OEM4-G2-3111RS
OEM4-G2-3111W	OEM4-G2-3111W-API
OEM4-G2-3111WS	OEM4-G2-3151R
OEM4-G2-3151R-API	OEM4-G2-3151W
OEM4-G2-3151W-API	OEM4-G2-EGNOS
OEM4-G2-EGNOS-API	OEM4-G2-GENERIC
OEM4-G2-L1L2	OEM4-G2-L1L2-API
OEM4-G2-L1L2W	OEM4-G2-L1L2W-API
OEM4-G2-LB+WAASHPBA	OEM4-G2-LB+WAASLBA
OEM4-G2-MSAS	OEM4-G2-MSAS-API
OEM4-G2-RT2	OEM4-G2-RT20
OEM4-G2-RT20-API	OEM4-G2-RT20W
OEM4-G2-RT20W-API	OEM4-G2-RT2-API
OEM4-G2-RT2S	OEM4-G2-RT2W
OEM4-G2-RT2W-API	OEM4-G2-RT2Wi
OEM4-G2-TSYNC	OEM4-G2-TSYNC-3151W
OEM4-G2-TSYNC-L1L2W	OEM4-G2-WAAS
OEM4-G2-WAAS-API	OEM4-G2-WAASHPBA
OEM4-G2-WAASLBA	

OEM4-G2L Card

End of Life Announcement: 30 October 2006
Last Time Buy: 28 February 2007
Standard End of Service: 31 October 2011
Replacement Product: OEMV-2

Affected Models

01017213	OEM4-G2L-3111R
OEM4-G2L-3111R-API	OEM4-G2L-3111RS
OEM4-G2L-3111W	OEM4-G2L-3111W-API
OEM4-G2L-3151R	OEM4-G2L-3151R-API
OEM4-G2L-3151W	OEM4-G2L-3151W-API
OEM4-G2L-EGNOS	OEM4-G2L-EGNOS-API
OEM4-G2L-GENERIC	OEM4-G2L-L1L2
OEM4-G2L-L1L2-API	OEM4-G2L-L1L2S
OEM4-G2L-L1L2S-API	OEM4-G2L-L1L2W
OEM4-G2L-L1L2W-API	OEM4-G2L-MSAS
OEM4-G2L-MSAS-API	OEM4-G2L-RT2
OEM4-G2L-RT2[INSITU]	OEM4-G2L-RT20
OEM4-G2L-RT20-API	OEM4-G2L-RT20W
OEM4-G2L-RT20W-API	OEM4-G2L-RT2-API
OEM4-G2L-RT2S	OEM4-G2L-RT2W
OEM4-G2L-RT2W-API	OEM4-G2L-RT2Wi
OEM4-G2L-WAAS	OEM4-G2L-WAAS-API

SUPERSTAR II Cards

Cards with straight, reverse, and right-angle connectors

End of Life Announcement: 29 May 2008
Last Time Buy: 31 July 2008
Standard End of Service: 30 June 2011
Replacement Product: SMART-V1

Affected Models

100-601943-001	245-601944-016
245-604090-011	245-604090-013
245-604090-031	245-604090-033
245-604090-111	245-604090-113
245-604090-116	245-604090-131
245-604090-133	245-604090-153
245-604090-915	SSII-3-10CP-19
SSII-3-1CPN	SSII-3-1CPN-19
SSII-3-1CPT	SSII-3-1CPT-19
SSII-3-5CP-19	SSII-3-5CPN-19
SSII-3-5HZ	SSII-3-5HZN
SSII-3-BASE	SSII-3-BASEN
SSII-3ET-1CPT	SSII-3RARF-1CPT
SSII-3RARF-1CPT-19	SSII-3RARF-5HZ
SSII-3RARF-BASE	SSII-3RARF-MTECH
SSII-3RARF-SAAB	SSII-3RARF-STD
SSII-3-STD	SSII-3-STDN
SSII-5-10CP-19	SSII-5-1CPN
SSII-5-1CPN-19	SSII-5-1CPT
SSII-5-1CPT-19	SSII-5-5CP-19
SSII-5-5CPN-19	SSII-5-5HZ
SSII-5-5HZN	SSII-5-BASE
SSII-5-BASEN	SSII-5RARF-1CPT-19
SSII-5RARF-SEATEX	SSII-5RARF-STD
SSII-5RARF-STD[GEN]	SSII-5REV-1CPT-19
SSII-5REV-5HZ	SSII-5REV-PROLINK
SSII-5-STD	SSII-5-STDN
SSII-5-UPLINK	



Enclosure

BDS IMUs and Software

End of Life Announcement: 3 August 2004
Last Time Buy: 3 August 2004
Standard End of Service: 3 August 2009
Replacement Product: SPAN Technology

Affected Models
 01016331

DL-4

End of Life Announcement: 3 August 2004
Last Time Buy: 29 October 2004
Standard End of Service: 3 August 2009
Replacement Product: DL-V3

Affected Models
 01016674
 DL-4-3111R
 DL-4-3151R
 DL-4-L1L2
 DL-4-RT2
 DL-4-RT2W
 01017028
 DL-4-3111RS
 DL-4-GENERIC
 DL-4-L1L2W
 DL-4-RT20
 DL-4-WAAS

DL-4plus Enclosure

End of Life Announcement: 7 March 2008
Last Time Buy: 15 September 2008
Standard End of Service: 7 March 2013
Replacement Product: DL-V3

Affected Models
 01017417
 DL-4+3111R
 DL-4+3111RS
 DL-4+3111W-A
 DL-4+3151R-A
 DL-4+3151W
 DL-4+424-3111R
 DL-4+424-3111W
 DL-4+424-3151R
 DL-4+424-3151W
 DL-4+424-EGNOS
 DL-4+424-GENERIC
 DL-4+424-L1L2-A
 DL-4+424-L1L2W-A
 DL-4+424-MSAS-A
 DL-4+424-RT20
 DL-4+424-RT20W
 DL-4+424-RT2-A
 DL-4+424-RT2W-A
 DL-4+424-RT2Wi-A
 DL-4+424-WAAS-A
 DL-4+EGNOS-A
 DL-4+GENERIC
 DL-4+L1L2
 DL-4+L1L2S
 DL-4+L1L2W-A
 DL-4+MSAS-A
 DL-4+RT20
 DL-4+RT20W
 DL-4+RT2-A
 DL-4+RT2WA
 DL-4+RT2Wi
 DL-4+WAAS
 UG-DL-4+422-RT2Wi
 01017454
 DL-4+3111R-A
 DL-4+3111W
 DL-4+3151R
 DL-4+3151RS
 DL-4+3151W-A
 DL-4+424-3111R-A
 DL-4+424-3111W-A
 DL-4+424-3151R-A
 DL-4+424-3151W-A
 DL-4+424-EGNOS-A
 DL-4+424-L1L2
 DL-4+424-L1L2W
 DL-4+424-MSAS
 DL-4+424-RT2
 DL-4+424-RT20-A
 DL-4+424-RT20W-A
 DL-4+424-RT2W
 DL-4+424-RT2Wi
 DL-4+424-WAAS
 DL-4+EGNOS
 DL-4+GENERIC
 DL-4+L1L2-A
 DL-4+L1L2W
 DL-4+MSAS
 DL-4+RT2
 DL-4+RT20-A
 DL-4+RT20W-A
 DL-4+RT2W
 DL-4+RT2W-A
 DL-4+RT2Wi-A
 DL-4+WAAS-A
 UG-DL-4+RT2Wi

EGNOS RIMS-C receiver

End of Life Announcement: 30 September 2003
Last Time Buy: 30 June 2004
Standard End of Service: 31 December 2009
Replacement Product: WAAS-G2

Affected Models
01016734 EGNOS-RECEIVER

Euro-L5 & EuroPak-L5

End of Life Announcement: 3 November 2005
Last Time Buy: 3 November 2005
Standard End of Service: 3 November 2010
Replacement Product: EuroPak-15a receiver

Affected Models
01017425 EUROPAK-L5-L5GEO

FlexPak-G2L

with OEM4-G2L card

End of Life Announcement: 30 October 2006
Last Time Buy: 28 February 2007
Standard End of Service: 31 October 2011
Replacement Product: FlexPak-V2

Affected Models

FLEXPAK-G2L-3111R	FLEXPAK-G2L-3111R-A
FLEXPAK-G2L-3111RS	FLEXPAK-G2L-3111W
FLEXPAK-G2L-3111W-A	FLEXPAK-G2L-3151R
FLEXPAK-G2L-3151R-A	FLEXPAK-G2L-3151W
FLEXPAK-G2L-3151W-A	FLEXPAK-G2L-EGNOS
FLEXPAK-G2L-EGNOS-A	FLEXPAK-G2L-GENERIC
FLEXPAK-G2L-L1L2	FLEXPAK-G2L-L1L2-A
FLEXPAK-G2L-L1L2W	FLEXPAK-G2L-L1L2W-A
FLEXPAK-G2L-MSAS	FLEXPAK-G2L-MSAS-A
FLEXPAK-G2L-RT2	FLEXPAK-G2L-RT20
FLEXPAK-G2L-RT20-A	FLEXPAK-G2L-RT20W
FLEXPAK-G2L-RT20W-A	FLEXPAK-G2L-RT2-A
FLEXPAK-G2L-RT2W	FLEXPAK-G2L-RT2W-A
FLEXPAK-G2L-RT2WS	FLEXPAK-G2L-WAAS
FLEXPAK-G2L-WAAS-A	

FlexPak-V1

End of Life Announcement: 30 January 2009
Last Time Buy: 31 August 2009
Standard End of Service: 31 December 2012
Replacement Product:

Affected Models

01017738	FLEXPAK-V1-1HZ
FLEXPAK-V1-CODE	FLEXPAK-V1-CODE-A
FLEXPAK-V1-CODE-S	FLEXPAK-V1-CODE-V
FLEXPAK-V1-CODE-V-A	FLEXPAK-V1-L1
FLEXPAK-V1-L1-A	FLEXPAK-V1-L1-F
FLEXPAK-V1-L1-S	FLEXPAK-V1-L1-V
FLEXPAK-V1-L1-V-A	FLEXPAK-V1-L1-VBS
FLEXPAK-V1-L1-VBS-A	FLEXPAK-V1-L1-VBS-S
FLEXPAK-V1-L1-VBS-V	FLEXPAK-V1-L1-VBS-V-A
FLEXPAK-V1-L1-V-F	FLEXPAK-V1-PVT
FLEXPAK-V1-PVT-A	FLEXPAK-V1-PVT-S
FLEXPAK-V1-PVT-V	FLEXPAK-V1-PVT-V-A
FLEXPAK-V1-RT20	FLEXPAK-V1-RT20-A
FLEXPAK-V1-RT20-F	FLEXPAK-V1-RT20-S
FLEXPAK-V1-RT20-V	FLEXPAK-V1-RT20-V-A
FLEXPAK-V1-RT20-V-F	FLEXPAK-V1-RTCM
FLEXPAK-V1-VBS	FLEXPAK-V1-VBS-A
FLEXPAK-V1-VBS-S	FLEXPAK-V1-VBS-V
FLEXPAK-V1-VBS-V-A	

FlexPak-V1G

End of Life Announcement: 30 January 2009
Last Time Buy: 31 August 2009
Standard End of Service: 31 December 2012
Replacement Product:

Affected Models

01017958	FLEXPAK-V1G-1HZ
FLEXPAK-V1G-1HZ-G	FLEXPAK-V1G-CODE
FLEXPAK-V1G-CODE-A	FLEXPAK-V1G-CODE-G
FLEXPAK-V1G-CODE-G-S	FLEXPAK-V1G-CODE-S
FLEXPAK-V1-GENERIC	FLEXPAK-V1G-GENERIC
FLEXPAK-V1G-G-Z	FLEXPAK-V1G-G-Z-A
FLEXPAK-V1G-HDG	FLEXPAK-V1G-HDG-A
FLEXPAK-V1G-L1	FLEXPAK-V1G-L1-A
FLEXPAK-V1G-L1-F	FLEXPAK-V1G-L1-G
FLEXPAK-V1G-L1-G[SEA]	FLEXPAK-V1G-L1-G-A
FLEXPAK-V1G-L1-G-F	FLEXPAK-V1G-L1-G-S
FLEXPAK-V1G-L1-G-V	FLEXPAK-V1G-L1-G-V-A
FLEXPAK-V1G-L1-G-V-F	FLEXPAK-V1G-L1-G-Z
FLEXPAK-V1G-L1-G-Z-A	FLEXPAK-V1G-L1-S
FLEXPAK-V1G-L1-V	FLEXPAK-V1G-L1-V-A
FLEXPAK-V1G-L1-V-F	FLEXPAK-V1G-PVT
FLEXPAK-V1G-PVT-A	FLEXPAK-V1G-PVT-G
FLEXPAK-V1G-PVT-G-S	FLEXPAK-V1G-PVT-G-Z
FLEXPAK-V1G-PVT-G-Z-A	FLEXPAK-V1G-PVT-S
FLEXPAK-V1G-RT20	FLEXPAK-V1G-RT20-A
FLEXPAK-V1G-RT20-F	FLEXPAK-V1G-RT20-G
FLEXPAK-V1G-RT20-G-A	FLEXPAK-V1G-RT20-G-F
FLEXPAK-V1G-RT20-G-S	FLEXPAK-V1G-RT20-G-V
FLEXPAK-V1G-RT20-G-V-A	FLEXPAK-V1G-RT20-S
FLEXPAK-V1G-RT20-V	FLEXPAK-V1G-RT20-V-A
FLEXPAK-V1G-RT2L1-G	FLEXPAK-V1G-RT2L1-G-A

FlexPak-V2

End of Life Announcement: 30 January 2009
Last Time Buy: 31 August 2009
Standard End of Service: 31 December 2012
Replacement Product:

Affected Models

01017740	FLEXPAK-V2-GENERIC
FLEXPAK-V2-G-Z	FLEXPAK-V2-G-Z-A
FLEXPAK-V2-HDG	FLEXPAK-V2-HDG-A
FLEXPAK-V2-L1	FLEXPAK-V2-L1-A
FLEXPAK-V2-L1-F	FLEXPAK-V2-L1-G
FLEXPAK-V2-L1-G-A	FLEXPAK-V2-L1-G-F
FLEXPAK-V2-L1-G-S	FLEXPAK-V2-L1-G-S-A
FLEXPAK-V2-L1-G-Z	FLEXPAK-V2-L1-G-Z-A
FLEXPAK-V2-L1L2	FLEXPAK-V2-L1L2[INSITU]
FLEXPAK-V2-L1L2-A	FLEXPAK-V2-L1L2-F
FLEXPAK-V2-L1L2-G	FLEXPAK-V2-L1L2-G[SEA]
FLEXPAK-V2-L1L2-G-A	FLEXPAK-V2-L1L2-G-F
FLEXPAK-V2-L1L2-G-S	FLEXPAK-V2-L1L2-G-S-A
FLEXPAK-V2-L1L2-G-Z	FLEXPAK-V2-L1L2-G-Z-A
FLEXPAK-V2-L1L2-S	FLEXPAK-V2-L1L2-S-A
FLEXPAK-V2-L1L2-Z	FLEXPAK-V2-L1L2-Z-A
FLEXPAK-V2-L1-S	FLEXPAK-V2-L1-S-A
FLEXPAK-V2-RT2	FLEXPAK-V2-RT20
FLEXPAK-V2-RT20-A	FLEXPAK-V2-RT20-F
FLEXPAK-V2-RT20-G	FLEXPAK-V2-RT20-G-A
FLEXPAK-V2-RT20-G-F	FLEXPAK-V2-RT20-G-S
FLEXPAK-V2-RT20-G-S-A	FLEXPAK-V2-RT20-S
FLEXPAK-V2-RT20-S-A	FLEXPAK-V2-RT2-A
FLEXPAK-V2-RT2-F	FLEXPAK-V2-RT2-G
FLEXPAK-V2-RT2-G-A	FLEXPAK-V2-RT2-G-F
FLEXPAK-V2-RT2-G-S	FLEXPAK-V2-RT2-G-S-A
FLEXPAK-V2-RT2L1-G	FLEXPAK-V2-RT2L1-G-A
FLEXPAK-V2-RT2-S	FLEXPAK-V2-RT2-S-A
FLEXPAK-V2-SBAS	FLEXPAK-V2-SBAS-A
FLEXPAK-V2-SBAS-Z	FLEXPAK-V2-SBAS-Z-A

GPStation Euro4-222

End of Life Announcement: 30 August 2004
Last Time Buy: 30 August 2004
Standard End of Service: 30 August 2009
Replacement Product: GPStation-G2

Affected Models
 GPSTATION-4E-SCINT GPSTATION-4E-SCINTW

GUS receiver

End of Life Announcement: 30 September 2003
Last Time Buy: 30 June 2004
Standard End of Service: 30 December 2009
Replacement Product:

Affected Models
 01016477

MPC

End of Life Announcement:
Last Time Buy: 30 June 2003
Standard End of Service: 30 June 2008
Replacement Product:

Affected Models
 01017096

MSAS receiver

End of Life Announcement: 30 September 2003
Last Time Buy: 30 June 2004
Standard End of Service: 31 December 2009
Replacement Product:

Affected Models
 01016637

NES receiver

End of Life Announcement: 30 September 2003
Last Time Buy: 30 June 2004
Standard End of Service: 31 December 2009
Replacement Product:

Affected Models
 01016638

ProPak-G2-DB9

End of Life Announcement: 3 August 2004
Last Time Buy: 29 October 2004
Standard End of Service: 3 August 2009
Replacement Product: ProPak-V3

Affected Models
 PROPAK-G2-DB9-3111R PROPAK-G2-DB9-3111R-A
 PROPAK-G2-DB9-3151R PROPAK-G2-DB9-3151W
 PROPAK-G2-DB9-424-3151W PROPAK-G2-DB9-424-GENERIC
 PROPAK-G2-DB9-424-L1L2 PROPAK-G2-DB9-424-L1L2W
 PROPAK-G2-DB9-EGNOS PROPAK-G2-DB9-GENERIC
 PROPAK-G2-DB9-L1L2 PROPAK-G2-DB9-L1L2W
 PROPAK-G2-DB9-L1L2W-A PROPAK-G2-DB9-RT2
 PROPAK-G2-DB9-RT20 PROPAK-G2-DB9-RT20W
 PROPAK-G2-DB9-RT2W PROPAK-G2-DB9-RT2W-A
 PROPAK-G2-DB9-WAAS

ProPak-G2-LEMO

End of Life Announcement: 3 November 2005
Last Time Buy: 3 November 2005
Standard End of Service: 3 November 2010
Replacement Product: ProPak-V3

Affected Models
 PROPAK-G2-LEMO-3111R PROPAK-G2-LEMO-3151R
 PROPAK-G2-LEMO-3151W PROPAK-G2-LEMO-GENERIC
 PROPAK-G2-LEMO-L1L2 PROPAK-G2-LEMO-RT2
 PROPAK-G2-LEMO-RT2W

ProPak-G2-LEMO-25-xxx

End of Life Announcement: 16 March 2009
Last Time Buy: 16 March 2009
Standard End of Service: 30 April 2012
Replacement Product: ProPak-V3

Affected Models

01017523 PROPAK-G2-LEMO-25-GENERIC
 PROPAK-G2-LEMO-25-RT2S

ProPak-G2plus

End of Life Announcement: 30 October 2006
Last Time Buy: 28 February 2007
Standard End of Service: 31 October 2011
Replacement Product: ProPak-V3

Affected Models

01017453 PROPAK-G2+DB9-3111R
 PROPAK-G2+DB9-3111R-A PROPAK-G2+DB9-3111W
 PROPAK-G2+DB9-3111W-A PROPAK-G2+DB9-3151R
 PROPAK-G2+DB9-3151R-A PROPAK-G2+DB9-3151W
 PROPAK-G2+DB9-3151W-A PROPAK-G2+DB9-424-3111R
 PROPAK-G2+DB9-424-3111R-A PROPAK-G2+DB9-424-3111W
 PROPAK-G2+DB9-424-3111W-A PROPAK-G2+DB9-424-3151R
 PROPAK-G2+DB9-424-3151R-A PROPAK-G2+DB9-424-3151W
 PROPAK-G2+DB9-424-3151W-A PROPAK-G2+DB9-424-EGNOS
 PROPAK-G2+DB9-424-EGNOS-A PROPAK-G2+DB9-424-GENERIC
 PROPAK-G2+DB9-424-L1L2 PROPAK-G2+DB9-424-L1L2-A
 PROPAK-G2+DB9-424-L1L2W PROPAK-G2+DB9-424-L1L2W-A
 PROPAK-G2+DB9-424-MSAS PROPAK-G2+DB9-424-MSAS-A
 PROPAK-G2+DB9-424-RT2 PROPAK-G2+DB9-424-RT20
 PROPAK-G2+DB9-424-RT20-A PROPAK-G2+DB9-424-RT20W
 PROPAK-G2+DB9-424-RT20W-API PROPAK-G2+DB9-424-RT2-A
 PROPAK-G2+DB9-424-RT2W PROPAK-G2+DB9-424-RT2W-A
 PROPAK-G2+DB9-424-RT2Wi PROPAK-G2+DB9-424-RT2Wi-A
 PROPAK-G2+DB9-424-WAAS PROPAK-G2+DB9-424-WAAS-A
 PROPAK-G2+DB9-EGNOS PROPAK-G2+DB9-EGNOS-A
 PROPAK-G2+DB9-GENERIC PROPAK-G2+DB9-L1L2
 PROPAK-G2+DB9-L1L2-A PROPAK-G2+DB9-L1L2W
 PROPAK-G2+DB9-L1L2W-A PROPAK-G2+DB9-MSAS
 PROPAK-G2+DB9-MSAS-A PROPAK-G2+DB9-RT2
 PROPAK-G2+DB9-RT20 PROPAK-G2+DB9-RT20-A
 PROPAK-G2+DB9-RT20W PROPAK-G2+DB9-RT20W-API
 PROPAK-G2+DB9-RT2-A PROPAK-G2+DB9-RT2W
 PROPAK-G2+DB9-RT2W-A PROPAK-G2+DB9-RT2Wi
 PROPAK-G2+DB9-RT2Wi-A PROPAK-G2+DB9-RT2WS
 PROPAK-G2+DB9-WAAS PROPAK-G2+DB9-WAAS-A
 UG-PROPAK-G2+DB9-424-RT2Wi UG-PROPAK-G2+DB9-RT2Wi

ProPak-LBplus

End of Life Announcement: 30 October 2006
Last Time Buy: 28 February 2007
Standard End of Service: 31 October 2011
Replacement Product: ProPak-V3

Affected Models

01017455 PROPAK-LB+GENERIC
 PROPAK-LB+HP PROPAK-LB+HP-A
 PROPAK-LB+HP-L1L2 PROPAK-LB+HP-L1L2-A
 PROPAK-LB+HP-RT2 PROPAK-LB+HP-RT2-A
 PROPAK-LB+HP-RT2Wi PROPAK-LB+HP-RT2Wi-A
 PROPAK-LB+HPS PROPAK-LB+VBS
 PROPAK-LB+VBS-A PROPAK-LB+VBS-L1
 PROPAK-LB+VBS-L1-A PROPAK-LB+VBS-RT20
 PROPAK-LB+VBS-RT20-A PROPAK-LB+VBS-S
 PROPAK-LB+XP PROPAK-LB+XP-A
 UG-PROPAK-LB+HP-RT2i

SUPERSTAR II FlexPak Enclosure

End of Life Announcement: 29 May 2008
Last Time Buy: 31 July 2008
Standard End of Service: 30 June 2011
Replacement Product: FlexPak-V1

Affected Models

241-600249-002	FLEXPAK-SSII-10CP-19
FLEXPAK-SSII-1CPN	FLEXPAK-SSII-1CPN-19
FLEXPAK-SSII-1CPT	FLEXPAK-SSII-1CPT-19
FLEXPAK-SSII-5CP-19	FLEXPAK-SSII-5CPN-19
FLEXPAK-SSII-5HZ	FLEXPAK-SSII-5HZN
FLEXPAK-SSII-BASE	FLEXPAK-SSII-BASEN
FLEXPAK-SSII-STD	FLEXPAK-SSII-STDN

SUPERSTAR II Receiver Development Kit

End of Life Announcement: 29 May 2008
Last Time Buy: 31 July 2008
Standard End of Service: 30 June 2011
Replacement Product: OEMV-1 and FlexPak-V1 with API

Affected Models

241-600249-100	DK-FLEXPAK-SSII-10CP-19
DK-FLEXPAK-SSII-1CPN	DK-FLEXPAK-SSII-1CPN-19
DK-FLEXPAK-SSII-1CPT	DK-FLEXPAK-SSII-1CPT-19
DK-FLEXPAK-SSII-5CP-19	DK-FLEXPAK-SSII-5CPN-19
DK-FLEXPAK-SSII-5HZ	DK-FLEXPAK-SSII-5HZN
DK-FLEXPAK-SSII-BASE	DK-FLEXPAK-SSII-BASEN
DK-FLEXPAK-SSII-STD	DK-FLEXPAK-SSII-STDN

UPC Receiver

End of Life Announcement: 30 September 2003
Last Time Buy: 30 June 2004
Standard End of Service: 31 December 2009
Replacement Product: GUST receiver

Affected Models

01017137	UPC-RECEIVER
----------	--------------

WAAS Receiver

End of Life Announcement: 30 September 2003
Last Time Buy: 30 June 2004
Standard End of Service: 31 December 2009
Replacement Product: WAAS-G2

Affected Models

01016247	WAAS-RECEIVER
----------	---------------

Webrider

End of Life Announcement:
Last Time Buy: 31 July 2003
Standard End of Service: 25 July 2008
Replacement Product:

Affected Models

14323056



SMART Antenna

SA-422-RM

End of Life Announcement: 29 June 2007
Last Time Buy:
Standard End of Service: 29 June 2012
Replacement Product: SMART-V1

Affected Models
 SA-422-RM-1CPT-19

SSII SMART Antenna with white 6-pin connector

End of Life Announcement: 18 November 2004
Last Time Buy: 18 February 2005
Standard End of Service: 18 November 2009
Replacement Product: SMART-V1

Affected Models
 100-601903-002 100-601911-022
 SA-232-06W-5HZ

SUPERSTAR II SMART Antenna

End of Life Announcement: 29 May 2008
Last Time Buy: 31 July 2008
Standard End of Service: 30 June 2011
Replacement Product: SMART-V1

Affected Models
 100-601903-052 100-601907-102
 100-601907-153 100-601910-002
 100-601910-012 100-601910-112
 100-601911-002 100-601911-012
 100-601911-102 100-601911-112
 9060-1441 SA-232-06G-1CPN
 SA-232-06G-1CPN-19 SA-232-06G-1CPT
 SA-232-06G-1CPT-19 SA-232-06G-5CP-19
 SA-232-06G-5CPN-19 SA-232-06G-5HZ
 SA-232-06G-5HZN SA-232-06G-STD
 SA-232-06G-STDN SA-232-07W-1CPN
 SA-232-07W-1CPN-19 SA-232-07W-1CPT
 SA-232-07W-1CPT-19 SA-232-07W-5CP-19
 SA-232-07W-5CPN-19 SA-232-07W-5HZ
 SA-232-07W-5HZN SA-232-07W-STD
 SA-232-07W-STDN SA-422-12W-1CPN
 SA-422-12W-1CPN-19 SA-422-12W-1CPT
 SA-422-12W-1CPT-19 SA-422-12W-5CP-19
 SA-422-12W-5CPN-19 SA-422-12W-5HZ
 SA-422-12W-5HZN SA-422-12W-BASE
 SA-422-12W-BASEN SA-422-12W-STD
 SA-422-12W-STDN SA-422-CMW-1CPN
 SA-422-CMW-1CPN-19 SA-422-CMW-1CPT
 SA-422-CMW-1CPT-19 SA-422-CMW-5CP-19
 SA-422-CMW-5CPN-19 SA-422-CMW-5HZ
 SA-422-CMW-5HZN SA-422-CMW-BASE
 SA-422-CMW-BASEN SA-422-CMW-STD
 SA-422-CMW-STDN SA-422-CSW-1CPT

SUPERSTAR II SMART Antenna Development Kit

End of Life Announcement: 29 May 2008
Last Time Buy: 31 July 2008
Standard End of Service: 30 June 2011
Replacement Product: SMART-V1 with API

Affected Models

DK-SA-232-06G-1CPN	DK-SA-232-06G-1CPN-19
DK-SA-232-06G-1CPT	DK-SA-232-06G-1CPT-19
DK-SA-232-06G-5CP-19	DK-SA-232-06G-5CPN-19
DK-SA-232-06G-5HZ	DK-SA-232-06G-5HZN
DK-SA-232-06G-STD	DK-SA-232-06G-STDN
DK-SA-232-07W-10CP-19	DK-SA-232-07W-1CPN
DK-SA-232-07W-1CPN-19	DK-SA-232-07W-1CPT
DK-SA-232-07W-1CPT-19	DK-SA-232-07W-5CP-19
DK-SA-232-07W-5CPN-19	DK-SA-232-07W-5HZ
DK-SA-232-07W-5HZN	DK-SA-232-07W-STD
DK-SA-232-07W-STDN	DK-SA-422-12W-10CP-19
DK-SA-422-12W-1CPN	DK-SA-422-12W-1CPN-19
DK-SA-422-12W-1CPT	DK-SA-422-12W-1CPT-19
DK-SA-422-12W-5CP-19	DK-SA-422-12W-5CPN-19
DK-SA-422-12W-5HZ	DK-SA-422-12W-5HZN
DK-SA-422-12W-BASE	DK-SA-422-12W-BASEN
DK-SA-422-12W-STD	DK-SA-422-12W-STDN



IMU

BDS IMUs and Software

End of Life Announcement:	3 August 2004	Affected Models	
Last Time Buy:	3 August 2004	80023510	80023512
Standard End of Service:	3 August 2009	80023513	BDS
Replacement Product:	SPAN Technology	BDS-IMU-11	BDS-IMU-17
		BDS-IMU-XX	

IMU-LB-Hxx

End of Life Announcement:	31 March 2007	Affected Models	
Last Time Buy:	30 June 2007	IMU-LB-000	IMU-LB-H58
Standard End of Service:	31 March 2012	IMU-LB-H62	
Replacement Product:	IMU-Hxx		

SPAN HG1700 IMU (DL-4+)

End of Life Announcement:	7 March 2008	Affected Models	
Last Time Buy:	15 September 2008	01017404	IMU-G2-000
Standard End of Service:	7 March 2013	IMU-G2-H58	IMU-G2-H62
Replacement Product:	HG1700 for OEMV		

SPAN HG1700 IMU Legacy Parts

End of Life Announcement:	7 March 2008	Affected Models	
Last Time Buy:	15 September 2008	IMU-G2-H11	IMU-G2-H17
Standard End of Service:	7 March 2013		
Replacement Product:	IMU-Hxx		



Software

RT-Static

development module for RTKNav

End of Life Announcement:

Last Time Buy: 9 January 2009

Standard End of Service: 31 July 2010

Replacement Product:

Affected Models

SW-RT-STC-U



Antenna

ANT-532-C

End of Life Announcement:	7 March 2008	Affected Models	
Last Time Buy:	7 March 2008	ANT-532-C	
Standard End of Service:	7 March 2013		
Replacement Product:	ANT-A72GA-TW-N		

ANT-533

End of Life Announcement:	7 March 2008	Affected Models	
Last Time Buy:	7 March 2008	ANT-533	ANT-533G
Standard End of Service:	7 March 2013		
Replacement Product:	ANT-C2GA-TW-N		

ANT-533-N

End of Life Announcement:	7 March 2008	Affected Models	
Last Time Buy:	7 March 2008	ANT-533-N	
Standard End of Service:	7 March 2013		
Replacement Product:	ANT-C2GA-NW-N		

ANT-534-C

End of Life Announcement:	7 March 2008	Affected Models	
Last Time Buy:	7 March 2008	ANT-534-C	
Standard End of Service:	7 March 2013		
Replacement Product:	ANT-A72GLA4-TW-N		

ANT-536-C

End of Life Announcement:	7 March 2008	Affected Models	
Last Time Buy:	7 March 2008	ANT-536-C	
Standard End of Service:	7 March 2013		
Replacement Product:	ANT-35C1GA-TW-N		

ANT-536SS-C

End of Life Announcement:	7 March 2008	Affected Models	
Last Time Buy:	7 March 2008	ANT-536SS-C	
Standard End of Service:	7 March 2013		
Replacement Product:	ANT-35C1GA-TW-SS-N		

ANT-537

End of Life Announcement:	7 March 2008	Affected Models	
Last Time Buy:	7 March 2008	ANT-537	
Standard End of Service:	7 March 2013		
Replacement Product:	ANT-26C1GA-TBW-N		

ANT-538(-C)

End of Life Announcement:	7 March 2008	Affected Models	
Last Time Buy:	7 March 2008	ANT-538	ANT-538-C
Standard End of Service:	7 March 2013		
Replacement Product:	ANT-35C50P1GLA-TW-N		

GPS-502

L1/L2 kinematic antenna

End of Life Announcement:	14 April 2004	Affected Models	
Last Time Buy:	13 April 2004	GPS-502	
Standard End of Service:	14 April 2009		
Replacement Product:	GPS-702-GG		

GPS-503

L1/L2 geodetic antenna with built-in choke ring

End of Life Announcement:	3 August 2004	Affected Models	
Last Time Buy:	1 December 2006	GPS-503	
Standard End of Service:	3 August 2009		
Replacement Product:	ANT-C2GA-TW-N		

GPS-504

GPS/GLONASS L1 antenna

End of Life Announcement:	31 July 2003	Affected Models	
Last Time Buy:	31 July 2003	GPS-504	
Standard End of Service:	30 June 2008		
Replacement Product:			

GPS-511

L1 aircraft antenna

End of Life Announcement:	3 August 2004	Affected Models	
Last Time Buy:	1 December 2006	GPS-511	
Standard End of Service:	3 August 2009		
Replacement Product:	ANT-A72GA-TW-N		

GPS-512

L1/L2 aircraft antenna

End of Life Announcement:	3 August 2004	Affected Models	
Last Time Buy:	1 December 2006	GPS-512	GPS-512-C
Standard End of Service:	3 August 2009		
Replacement Product:	ANT-A72GA-TW-N		

GPS-514

L1/L2 aviation antenna

End of Life Announcement:	31 July 2003	Affected Models	
Last Time Buy:	31 July 2003	GPS-514	
Standard End of Service:	30 June 2008		
Replacement Product:			

GPS-521

L1 automotive antenna

End of Life Announcement: 8 December 2006**Last Time Buy:** 8 March 2007**Standard End of Service:** 8 December 2011**Replacement Product:** ANT-26C1GA-TBW-N**Affected Models**

GPS-521

GPS-531

L1 kinematic antenna

End of Life Announcement: 14 April 2004**Last Time Buy:** 13 April 2004**Standard End of Service:** 14 April 2009**Replacement Product:** GPS-702-GG**Affected Models**

GPS-531

GPS-532

L1/L2 aircraft antenna

End of Life Announcement: 8 December 2006**Last Time Buy:** 8 March 2007**Standard End of Service:** 8 December 2011**Replacement Product:** ANT-A72GA-TW-N**Affected Models**

GPS-532

GPS-532-C

GPS-533

L1/L2 geodetic antenna with choke ring

End of Life Announcement: 8 December 2006**Last Time Buy:** 8 March 2007**Standard End of Service:** 8 December 2011**Replacement Product:** ANT-C2GA-TW-N**Affected Models**

GPS-533

GPS-533-N

GPS-534

L1/L2/L-band aircraft antenna

End of Life Announcement: 8 December 2006**Last Time Buy:** 8 March 2007**Standard End of Service:** 8 December 2011**Replacement Product:** ANT-A72GA-TW-N**Affected Models**

GPS-534

GPS-534-C

GPS-536-C

L1 aircraft antenna

End of Life Announcement: 4 July 2007**Last Time Buy:** 4 July 2007**Standard End of Service:** 4 July 2012**Replacement Product:** ANT-35C1GA-TW-N**Affected Models**

GPS-536-C

GPS-537

L1 automotive antenna

End of Life Announcement: 4 July 2007**Last Time Buy:** 4 July 2007**Standard End of Service:** 4 July 2012**Replacement Product:** ANT-26C1GA-TBW-N**Affected Models**

GPS-537

GPS-600-G

GPS/GLONASS L1/L2 antenna

End of Life Announcement: 31 July 2003
Last Time Buy: 31 July 2003
Standard End of Service: 30 June 2008
Replacement Product:

Affected Models
 GPS-600-G

GPS-600-LB

L1/L2/L-band antenna

End of Life Announcement: 10 June 2005
Last Time Buy: 12 August 2005
Standard End of Service: 10 June 2010
Replacement Product: GPS-702L

Affected Models
 500-0-0021 GPS-600-LB

GPS-600-X Antenna

passive antenna

End of Life Announcement:
Last Time Buy: 28 March 2003
Standard End of Service: 28 March 2008
Replacement Product:

Affected Models
 GPS-600-X

GPS-700 antennas

L1 & L1/L2 pinwheel antennas (GPS only)

End of Life Announcement: 22 June 2006
Last Time Buy: 30 September 2006
Standard End of Service: 30 September 2011
Replacement Product: GPS-701-GG & GPS-702-GG

Affected Models
 GPS-701 GPS-702
 NGS-702

L1 aviation antenna

End of Life Announcement: 5 July 2005
Last Time Buy: 30 September 2005
Standard End of Service: 5 July 2010
Replacement Product:

Affected Models
 201-990300-759

L1 marine and aviation antennas

End of Life Announcement: 18 November 2004
Last Time Buy: 18 February 2005
Standard End of Service: 18 November 2009
Replacement Product:

Affected Models
 201-990144-807 201-990146-789

SUPERSTAR II non-RoHS Antennas and Accessories

End of Life Announcement: 7 March 2008
Last Time Buy: 15 June 2008
Standard End of Service: 7 March 2013
Replacement Product: Antcom antennas and accessories

Affected Models
 201-990146-716 201-990147-432
 201-990147-606 201-990148-152



Cable

AC Adapters

general-purpose, non-RoHS compliant

End of Life Announcement:	18 November 2004	Affected Models	
Last Time Buy:	18 November 2004	40023098	40123112
Standard End of Service:	18 November 2009		
Replacement Product:	40023106		

Antenna Cable (GPS-C001)

End of Life Announcement:	2 November 2006	Affected Models	
Last Time Buy:	2 November 2006	GPS-C001	
Standard End of Service:	2 November 2011		
Replacement Product:			

Antenna cables

RF cables with male TNC connectors, not RoHS-compliant

End of Life Announcement:	31 July 2003	Affected Models	
Last Time Buy:	31 July 2003	01016644	GPS-C002
Standard End of Service:	30 June 2008	GPS-C005	GPS-C015
Replacement Product:		GPS-C030	GPS-C031

BDS IMUs and Software

End of Life Announcement:	3 August 2004	Affected Models	
Last Time Buy:	3 August 2004	01016569	01016829
Standard End of Service:	3 August 2009		
Replacement Product:	SPAN Technology		

DL Accessories

End of Life Announcement:	31 July 2003	Affected Models	
Last Time Buy:	31 July 2003	01016622	01016665
Standard End of Service:	25 July 2008	01016666	
Replacement Product:			

DL Power Cable

for dual batteries

End of Life Announcement:	20 November 2003	Affected Models	
Last Time Buy:	20 November 2003	01016690	
Standard End of Service:	21 November 2008		
Replacement Product:			

Euro4 cable

End of Life Announcement:	31 July 2003	Affected Models	
Last Time Buy:	31 July 2003	21323116	
Standard End of Service:	25 July 2008		
Replacement Product:			

GPS-ACDL adapters

DL-4 AC adapters

End of Life Announcement: 21 November 2003
Last Time Buy: 21 November 2003
Standard End of Service: 21 November 2008
Replacement Product: 40023106

Affected Models

GPS-ACDL GPS-ACDL-4

Hot swap and power cable

End of Life Announcement: 31 July 2003
Last Time Buy: 31 July 2003
Standard End of Service: 31 July 2008
Replacement Product:

Affected Models

01016460

MEDLL receiver cable

End of Life Announcement: 3 August 2004
Last Time Buy: 29 October 2004
Standard End of Service: 3 August 2009
Replacement Product: 60323062

Affected Models

60715062

PowerPak automotive adapter

End of Life Announcement: 3 August 2004
Last Time Buy: 29 October 2004
Standard End of Service: 3 August 2009
Replacement Product:

Affected Models

01014989

ProPak and DL strobe cable

End of Life Announcement: 3 August 2004
Last Time Buy: 29 October 2004
Standard End of Service: 3 August 2009
Replacement Product:

Affected Models

01016330

ProPak Power Cables

End of Life Announcement: 31 July 2003
Last Time Buy: 31 July 2003
Standard End of Service: 25 July 2008
Replacement Product:

Affected Models01016465 01016724
01016725**RF cables**

+12 & +26 dB, assorted lengths

End of Life Announcement: 1 April 2005
Last Time Buy: 1 April 2005
Standard End of Service: 1 April 2010
Replacement Product:

Affected Models217-601730-005 217-601730-015
217-601730-030**SPAN IMU-LN200 Accessories (non RoHS)**

End of Life Announcement: 30 October 2006
Last Time Buy: 28 February 2007
Standard End of Service: 30 October 2011
Replacement Product: RoHS-compliant cables: 01017821 (power); 01017822 (COM)

Affected Models

01017374 01017375

SSII SMART Antenna cables

End of Life Announcement: 5 July 2005
Last Time Buy: 30 September 2005
Standard End of Service: 5 July 2010
Replacement Product: RS-232 and RS-422 cables

Affected Models
217-601742-001 217-601742-004
217-601764-001 217-601798-001

Starbox I/O cable

End of Life Announcement: 14 April 2008
Last Time Buy: 14 April 2008
Standard End of Service: 14 April 2008
Replacement Product:

Affected Models
217-601729-002



Other

Compact Flash

1GB for industrial temperatures

End of Life Announcement: 3 November 2005

Last Time Buy: 3 November 2005

Standard End of Service: 3 November 2010

Replacement Product: 31324235

Affected Models

31324181

DL Accessories

End of Life Announcement: 31 July 2003

Last Time Buy: 31 July 2003

Standard End of Service: 25 July 2008

Replacement Product:

Affected Models

01016698

20023715

01016819

GPS-ACHG

GPS-28VDL

28 V power conditioner

End of Life Announcement: 31 July 2003

Last Time Buy: 31 July 2003

Standard End of Service: 31 July 2008

Replacement Product:

Affected Models

GPS-28VDL

GPS-28VDL-4

DL-4 power conditioner

End of Life Announcement: 1 April 2005

Last Time Buy: 1 April 2005

Standard End of Service: 1 April 2010

Replacement Product:

Affected Models

GPS-28VDL-4

GPS-A032

Attachable choke ring ground plane

End of Life Announcement: 13 April 2004

Last Time Buy: 13 April 2004

Standard End of Service: 13 April 2009

Replacement Product:

Affected Models

GPS-A032

LGF4-Eng

End of Life Announcement:

Last Time Buy: 31 July 2003

Standard End of Service: 25 July 2008

Replacement Product:

Affected Models

LGF4-ENG

Magnetic Antenna Mounts

End of Life Announcement:		Affected Models	
Last Time Buy:	1 March 2009	12023172	12023274
Standard End of Service:	31 December 2011		
Replacement Product:	Antcom products		

ProPak & PwrPak Power Accessories

End of Life Announcement:	31 July 2003	Affected Models	
Last Time Buy:	31 July 2003	01016464	GPS-APRO
Standard End of Service:	30 June 2008	GPS-APWR	
Replacement Product:	40023106		

SUPERSTAR II non-RoHS Antennas and Accessories

End of Life Announcement:	7 March 2008	Affected Models	
Last Time Buy:	15 June 2008	270-990146-890	530-990300-203
Standard End of Service:	7 March 2013		
Replacement Product:	Antcom antennas and accessories		

Webrider

End of Life Announcement:		Affected Models	
Last Time Buy:	31 July 2003	01016939	
Standard End of Service:	25 July 2008		
Replacement Product:			
